

Tom E. Tynan  
Vice President  
Vogtle -Units 1 & 2

Southern Nuclear  
Operating Company, Inc.  
7821 River Road  
Waynesboro, GA 30830

Tel 706.826.3151  
Fax 205.980.3321



June 5, 2014

Docket No.: 50-424

NL-14-0810

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555-0001

Vogtle Electric Generating Plant – Unit 1  
Licensee Event Report 2014-002-00  
Manual Reactor Trip due to Main Steam Isolation Valve Failure

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company (SNC) is submitting the enclosed Licensee Event Report, 2014-002-00. This letter contains no NRC commitments. If you have any questions, please contact George Gunn at (706) 848-3596.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "T. E. Tynan".

T. E. Tynan  
Vice President – Vogtle

TET/KDM

Enclosure: Unit 1 Licensee Event Report 2014-002-00

cc: Southern Nuclear Operating Company  
Mr. S. E. Kuczynski, Chairman, President & CEO  
Mr. D. G. Bost, Executive Vice President & Chief Nuclear Officer  
Mr. B. L. Ivey, Vice President – Regulatory Affairs  
Mr. D. R. Madison, Vice President – Fleet Operations  
Mr. C. R. Pierce, Regulatory Affairs Director  
Ms. M. A. Cline, Vogtle OE Coordinator  
RType: CVC7000

U. S. Nuclear Regulatory Commission  
Mr. V. M. McCree, Regional Administrator  
Mr. R. E. Martin, NRR Senior Project Manager - Vogtle  
Mr. L. M. Cain, Senior Resident Inspector – Vogtle

**Vogtle Electric Generating Plant – Unit 1  
Licensee Event Report 2014-002-00  
Manual Reactor Trip due to Main Steam Isolation Valve Failure**

**Enclosure**

**Unit 1 Licensee Event Report 2014-002-00**

**LICENSEE EVENT REPORT (LER)**(See Page 2 for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by Internet e-mail to [Infocollections.Resource@nrc.gov](mailto:Infocollections.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NE08-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

**1. FACILITY NAME**

Vogtle Electric Generating Plant – Unit 1

**2. DOCKET NUMBER**

05000 424

**3. PAGE**

1 OF 3

**4. TITLE**

Unit 1 Manual Reactor Trip due to Main Steam Isolation Valve Failure

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
4	12	14	2014	- 002	- 00	06	05	2014	FACILITY NAME	DOCKET NUMBER
										05000
										05000

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
1	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
10. POWER LEVEL  028	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

**12. LICENSEE CONTACT FOR THIS LER**

LICENSEE CONTACT	TELEPHONE NUMBER (Include Area Code)
Vogtle Electric Generating Plant / Karen Morrow, Licensing Engineer	(706) 848-3365

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
B	SB	ISV	R344	Y					

14. SUPPLEMENTAL REPORT EXPECTED	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO				

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

On 4/12/14 at 20:08, Unit 1 Reactor was manually tripped from 28 percent power. The manual trip occurred during power ascension following the 1R18 refueling outage. Control room operators received a Loop 1 Train B main steam isolation valve (MSIV) trouble annunciator followed by the MSIV not fully open annunciator. Control room operators recognized steam generator 1 level and loop 1 steam flow lowering and manually tripped the reactor.

Unit 1 was stabilized in Mode 3. Plant systems responded as expected with decay heat removal via Auxiliary Feedwater and steam discharge to the Main Condenser. Unit 2 was unaffected and there were no adverse effects on plant safety or on the health and safety of the public. This incident is of very low safety significance.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 60 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53) U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001 or by internet e-mail to [InfoCollectionResource@nrc.gov](mailto:InfoCollectionResource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NE08-10202, (3150-0104) Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Vogtle Electric Generating Plant – Unit 1	05000 0424	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3
		2014	- 002	- 00	

**NARRATIVE****A. REQUIREMENT FOR REPORT**

This report is required per 10CFR 50.73(a)(2)(iv)(A) due to an unplanned manual actuation of the Reactor Protection System (RPS) and automatic actuation of the Feedwater Isolation (FWI) Engineered Safety Features Actuation System (ESFAS).

**B. UNIT STATUS AT TIME OF EVENT**

Mode 1, 28 percent rated thermal power.

**C. DESCRIPTION OF EVENT**

On 4/12/14 at 20:08, Unit 1 Reactor was manually tripped from 28 percent power. The manual trip occurred during power ascension following the 1R18 refueling outage. Control room operators received a Loop 1 Train B main steam isolation valve (MSIV) trouble annunciator followed by the MSIV not fully open annunciator. Control room operators recognized steam generator 1 level and loop 1 steam flow lowering and manually tripped the reactor.

The direct cause of the event was a failed O-ring on the Loop 1 Train B MSIV lower manifold-to-cylinder mating surface resulting in a loss of hydraulic oil pressure. The root cause was misalignment of the lower manifold-to-cylinder mating surface during valve reassembly. Post-event test results from an independent laboratory concluded the pinched O-ring occurred as the lower manifold and the cylinder were connected and bolted together. The MSIV drifted closed to its fail safe position as hydraulic pressure lowered. Unit 1 was stabilized in Mode 3. Plant systems responded as expected with decay heat removal via Auxiliary Feedwater and steam discharge to the Main Condenser. Plant systems responded as expected and there were no adverse effects on plant safety or on the health and safety of the public. Unit 2 was unaffected.

**D. CAUSE OF EVENT**

The direct cause of the event was a failed O-ring on the Loop 1 Train B MSIV lower manifold-to-cylinder mating surface. This resulted in a loss of hydraulic oil pressure causing the MSIV to fail closed. The O-ring was pinched during reassembly of the lower manifold and cylinder following valve maintenance.

LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Vogtle Electric Generating Plant – Unit 1	05000 0424	YEAR	SEQUENTIAL NUMBER	REV NO	3 OF 3
		2014	- 002	- 00	

## NARRATIVE

## E. SAFETY ASSESSMENT

The MSIV failed to the closed position thereby fulfilling its designed safety function. Unit 1 was stabilized in Mode 3. Plant systems responded as expected with decay heat removal via Auxiliary Feedwater and steam discharge to the Main Condenser. There were no adverse effects on plant safety or on the health and safety of the public. This incident is of very low safety significance.

## F. CORRECTIVE ACTION

Maintenance instructions will be provided to ensure proper alignment of the lower manifold-to-cylinder mating surface to prevent damaging the O-ring during installation or valve reassembly.

## G. ADDITIONAL INFORMATION

## 1) Failed Components:

Component: ISV-Isolation Valve

## 2) Previous Similar Events:

Licensee Event Report 50-425/90-008-000, "Manual Reactor Trip Following MSIV Closure Due to O-ring Failure"

A similar event occurred at Vogtle Unit 2 in 1990. The cause for the MSIV closure was the failure of an O-ring sealing a connection on the non - pump side hydraulic manifold. Although failure modes were similar, rotary or oscillatory movement during re-assembly was not identified as a primary contributor.

## 3) Energy Industry Identification System Code:

Main/Reheat Steam System - SB